

D TO N/RAIL LEVEL 2. CDC

\* 27/04/07 07:39 JEGFC003 \* DISPUTED, PARTIAL ACCEPTANCE  
ATTRIBUTION ISSUES: 1) DISPUTE 1F06 ST.PANCRAS-WEST HAMP. THIS  
IS WAS DUE TO IT FOLLOWING 2002 WHICH WAS DIVERTED F/L AROUND  
D LATE 2000. 2) DISPUTE 2022 DELAY. THIS TRAIN WAS PINED AT  
KINGS X, BUT THE HEADCODE WAS NOT CHANGED. PLEASE CANCEL THE  
TRAIN THERE AND REMOVE THE DELAY.

GENERAL ISSUES. A) WAITING FOR PICTURES OF THE DAMAGED PART  
FROM CAULDWELL. B) NETWORK RAIL FREEFORM GIVES A DIFFERENT VIEW  
OF THE EVENT COMPARED TO THE DRIVER'S WRITTEN REPORT. WAITING  
FOR VOICE TAPES. DISPUTED AT 158 MINUTES. CDC

\* 26/04/07 13:44 JEGFC003 \* DISPUTED, INCORRECT MANAGER CODE  
NETWORK RAIL LEVEL 2 HAVE BEEN ASKED TO HAVE THE VOICE TAPES  
PULLED FOR THE DRIVER/SIGNALLER COMMUNICATIONS FOR THIS INCIDENT.  
CDC

\* 26/04/07 08:40 JEGFC118 \* CODE CHANGED  
RESPONSIBLE MANAGER CODE UPDATED FROM MEGA TO MEGI

\* 26/04/07 08:40 JEGFC118 \* DISPUTED, PARTIAL ACCEPTANCE  
PLEASE REFER TO LEVEL 2 PENDING FLEET AND DRIVER  
INVESTIGATION.GWG.

MB14117 27/09/07 15.12.10 U3531

Incident : 949912 3K21 AIR COCK DROPPED OFF

Created on: 26/04/07....hdr

No network delays

MB14117 27/09/07 15.12.10 U3527 hdr  
 TCTRJ82 TRUST Incident Details 27/09/07 15:12  
 Incident : 949912 3K21 AIR COCK DROPPED OFF Created on : 26/04/07  
 Section : WHMPSTDTK - STALBANSC (63451-63201) Start : 07:30 26/04/07  
 Delay Code: M6 EMU OTHER T&RS BRS Code : End : 07:40 26/04/07  
 Status : DISPUTED, INCORRECT MANAGER CODE Closed : 11:16 01/05/07  
 Last updated by: JQGP5039 at : 11:20 01/05/07  
 Equipment Number : 319007 Fault System/Nr. :  
 Location Text : RADLETT Responsible Train: 3K21  
 Railtrack Zone/Area: G19 WEST HAMPSTEAD PSB AREA NO NETWORK DELAYS  
 Railtrack Manager : OQGY WEST HAMPSTEAD DELIVERY UNIT  
 LATA : U916990 :  
 Responsible Manager: MEGI TLINK HIRED 319  
 LATA : DUMMY : Fax :  
 Update Status (A/D): Dispute Reason:  
 Comment:

SUMMARY	Full Cncl	Part Cncl	Trains Delayed	Delay Mins	FtS/Div
Direct/Reaction:	0/ 0	3/ 1	1/ 16	14/ 136	
TOTALS :	0	4	17	150	0

MB14117 27/09/07 15.12.10 U3528 hdr  
 Incident : 949912 3K21 AIR COCK DROPPED OFF Created on: 26/04/07

\*\*\* 26/04/07 07:51 JQGM2967 \*\*\* CREATED  
 3K21 STOPPED ON THE DOWN FAST LINE AT RADLETT JN, DRIVER REPORTS THAT THE AIR COCK HAS DROPPED OFF WHICH HAS CAUSED A BRAKE APPLICATION. DRIVER STATED HE DID NOT STRIKE ANYTHING. 2T 04 AND 2002 STOOD BEHIND. OTHER SERVICES DIVERTED SLOW LINE AROUND.  
 \*\*\* 26/04/07 07:53 JQGM2967 \*\*\* AMENDED  
 \*\*\* 26/04/07 08:17 JQGM3762 \*\*\* AMENDED  
 SRCT agreed with FCC commencing at 0731.  
 \*\*\* 26/04/07 13:10 JQGM3762 \*\*\* AMENDED  
 SRCT concluded by FCC at 1200  
 \*\*\* 27/04/07 09:16 JQGP5038 \*\*\* AMENDED  
 wham ssm advised DA. driver had not reported striking anything to the signaller. then after driver spoke to the fitter he reports he has.  
 \*\*\* 01/05/07 11:20 JQGP5039 \*\*\* AMENDED

MB14117 27/09/07 15.12.10 U3529 hdr  
 Incident : 949912 3K21 AIR COCK DROPPED OFF Created on: 26/04/07....

Train	Oper	Section affected	Delay	Status	Resp Train
26/04 2T04 0549 BRIGHTON	EG	WHMPSTDTK-STALBANSC	019	***	YD 3K21
26/04 2T06 0609 BRIGHTON	EG	WHMPSTDTK-STALBANSC	008	***	YD 872002M626
26/04 2002 0624 SUTTON	EG	WHMPSTDTK-STALBANSC	016	***	YD 872T04M526
26/04 2V98 0645 SELHURST	EG	WHMPSTDTK-STALBANSC	009	***	YD 631D07MB26
26/04 3K21 0705 MORGETLTK	EG	WHMPSTDTK-STALBANSC	014	***	
26/04 1J83 0708 BEDFORD	EG	STALBANSC-WHMPSTDTK	004	***	YB 631F06MA26
26/04 1F06 0725 STPANCRAS	HI	WHMPSTDTK-STALBANSC	009	***	YP 3K21
26/04 1D07 0730 STPANCRAS	HI	WHMPSTDTK-STALBANSC	009	***	YP 633K21MA26
26/04 2O21 0744 STALBANSC	EG	STALBANSC-BLACKFRS	Pt	cncl ***	
26/04 2T21 0748 BEDFORD	EG	WHMPSTDTK-KINGSXTLK	003	***	YD 632J10MC26
26/04 2A46 0752 BEDFORD	EG	WHMPSTDTK-KINGSXTLK	003	***	YD 632V27MC26
26/04 2A08 0752 STALBANSC	EG	KENTISHTN-MORGETLTK	Pt	cncl ***	
		STALBANSC	016	***	YI 872002M626
26/04 1D08 0755 STPANCRAS	HI	KETTERING-MARKETHBR	002	***	YD 631D07MB26
26/04 2O25 0758 BEDFORD	EG	WHMPSTDTK-KINGSXTLK	005	***	YD 622A44MC26
26/04 2A44 0802 LUTON	EG	STALBANSC-WHMPSTDTK	005	***	YD 632J10MC26
		WHMPSTDTK-KINGSXTLK	005	***	YD 2T21
26/04 2J10 0807 STALBANSC	EG	STALBANSC	007	***	YI 872V98M626
26/04 5J83 0820 BLACKFRS	EG	BLACKFRS -KINGSXTLK	Pt	cncl ***	YI .....
26/04 2V27 0822 STALBANSC	EG	WHMPSTDTK-KINGSXTLK	005	***	YD 622O25MB26
26/04 2O22 0923 WIMBLEDON	EG	KINGSXTLK-LUTON	Pt	cncl ***	
26/04 2O26 0954 WIMBLEDON	EG	WIMBLEDON	008	***	YI 622O25MB26

MB14117 27/09/07 15.12.10 U3530 hdr  
 Incident : 949912 3K21 AIR COCK DROPPED OFF Created on: 26/04/07

\* 01/05/07 11:16 JEGFC003 \* DISPUTED, INCORRECT MANAGER CODE